

Circle

Evaluation of the **Circle Town County Airport** yielded the following PCI values.

Section	Critical PCI	Surveyed PCIs				Predicted PCIs	
		1988	1991	1994	1997	2002	2007
A-1	55	XX	89	76	61	53	52
A-2	55	XX	96	87	56	52	51
R-1	55	XX	94	87	77	67	58
R-2	55	XX	97	96	78	67	59
T-1	55	XX	93	82	76	66	58
T-2	50	XX	73	74	60	50	34

Pavement Condition Index (PCI) to **Pavement Condition Rating** conversion:

0 ≤ **Failed** ≤ 10 < **Very Poor** ≤ 25 < **Poor** ≤ 40 < **Fair** ≤ 55 < **Good** ≤ 70 < **Very Good** ≤ 85 < **Excellent** ≤ 100

"XX" in PCI columns indicates previous PCI values have been voided to account for new construction.

No entry in PCI columns indicates no inspection of the pavement section for the year.

PCI predictions are based on the assumption that current maintenance practices will continue with no major reconstruction.

All your pavements are in "good" or better condition. Your aprons, and taxiway T-2 are forecast to drop below their critical PCI's within 5 years. Cracking, alligator cracking, and depressions are the main causes of your pavement degradation.